



Important – Read This First

- Some adjustment of the timing will be necessary by adjusting the potentiometers, installing the device at default values will result in errors.

**RC-04. POE.PowSup.Mag.REX.REXButton.
DSM.ADA-CADS1**

Dwg No:	Sheet 1	of 1
Date: 10-10-2017	Drawn By: David Tamarchenko	Version: 1.00.00

ISONAS
PURE IP ACCESS CONTROL

4750 Walnut Street Suite 110
Boulder, CO 80301
www.isonas.com