



---

**Product Release Information: IP Bridge 2.0 Firmware 1.19**

<b>Product</b>	IP Bridge 2.0
<b>Version Number</b>	1.19
<b>Firmware Release Date</b>	June 2022
<b>Customer Support</b>	For more information or support, visit the <a href="#">ISONAS</a> website.

**Attention:**

This document contains the **Release Notes** for IP Bridge 2.0 firmware version **1.19**. The version includes feature updates and improvements made after the firmware 1.17 released in June of 2021.

***Who should update?***

Allegion recommends keeping all devices at your site up to date with the latest firmware and software. We strive to provide the best products and service for our customers and security upgrades are highly recommended.

Our latest firmware and software releases will allow the customer to get the most from their devices.

Specifically, all customers who would be interested in the following Recent Change should update all the devices and mobile devices used at their site:

**Recent Changes:**

**PIC V1.03**

- Add support for adjustable "reset to normal" time
- Fix bug that caused valid admits during a scheduled lock event from activating the relay and unlocking the door
- Prevent REX / AUX status update messages during a 2-factor session from having 2-factor bits applied resulting in odd audit messages in the log

**Coldfire V1.19**

- Implement database corruption notification diagnostic message similar to RC04 to prevent activating a corrupt database from PureAccess
- Implement a coprocessor "heartbeat" health check system to identify communication issues and restore connections when errors occur

**RC RELEASE NOTES: IP Bridge 2.0 Firmware 1.19**

SES-20220617A



**ALLEGION™**

---

<b>Revision</b>	<b>COMMENTS</b>	<b>DATE</b>
SES20220617A	IP Bridge V2 Firmware Update	06/17/2022