



NOTE:
 1. THIS STRIKE IS NOT HANDED. LATCH BOLT
 OPENING IS OFFSET IN THE SAME DIRECTION
 FOR "LHR" AND "RHR" APPLICATION.

283 Strike Application for 98/9947-WDC,
 7547WDC, 7847WDC,
 33/3547-WDC, & 33/3547A-WDC

VON DUPRIN®

NOTES: SEE MASTER SHEET #10001 FOR SUGGESTED REINFORCING

TEMPLATE
 NUMBER:

W30230_b

DATE:
 04-15-24