



Product Release Information: LE Firmware 01.11.04

Product	LE
Version Number	01.11.04
Firmware Release Date	October 2021
Customer Support	For more information or support, visit the ENGAGE website.

Attention:

This document contains the **Release Notes** for LE device firmware version **01.11.04**. This version includes feature updates and improvements made after the LE product firmware 1.10.05 released in May of 2021.

Installation and Update Notes:

Device firmware updates are available October 2021 through the ENGAGE™ cloud database.

From the ENGAGE web portal, each lock may be independently selected by the site administrator to have the latest firmware downloaded during the next scheduled Wi-Fi connection. Alternatively, the site administrator may connect locally to individual locks with the ENGAGE mobile application to update an LE with the latest firmware.

Firmware versions that will be installed with this update:

- **Main Application** **01.11.04**
- **Reader Application** **02.10.00**
- *BLE Application* 02.13.06.327,01.10.03,01-1.7.0
- Wi-Fi Application: 02.10.0.0

NOTE: The **BOLD** item(s) are updated from the previous release

Other system components versions to be used with this release: (or newer)

- Gateway **01.61.02**
- MT20W 40.04.00
- Android Application **4.6.167**
- iOS application **3.7.0**
- ENGAGE **8.0.0**

LE RELEASE NOTES: LE Firmware 01.11.04

SES-20211023A



ALLEGION™

Who should update?

Allegion suggests that customers utilize the latest firmware release to take advantage of the latest functionality, bug fixes, and security enhancements. We strive to provide the best products and service for our customers.

Specifically, any customer interested in any of the following New Features and Recent Changes should update their LE lock firmware to version 01.11.04.

New Feature:

- Support Added for Android HCE Credential
 - Support has been added ahead of the Android HCE Credential to facilitate use when the credential becomes available

Recent Changes:

- Lock will no longer record a “Momentary Unlock” audit when a manual override command of Momentary Unlock is sent while the lock is in “Passage” state
- Fixed an issue to prevent the lock from being commissioned in construction mode
- Fixed for various import issues when working with Third-party Partners

Revision	COMMENTS	DATE
SES20211023A	Release Notes for LE as part of ENGAGE 8.0.0	10-23-2021