




NOTE: 1. FOR DEVICE FUNCTIONS SEE APPROPRIATE DEVICE TEMPLATES.

2. A COORDINATOR MUST BE USED ON INACTIVE DOOR.

1609 J Strike for 3327A/3527A Vertical Rod & 33A/35A Rim Series Devices

VON DUPRIN®

NOTES: SEE MASTER SHEET #10001 FOR SUGGESTED REINFORCING

TEMPLATE
NUMBER:

30030_a

DATE:
05-23-13