



Frame Preparation - 4754 & 4854  
Electric Disconnect Mullions

**VON DUPRIN®**

NOTES: SEE MASTER SHEET #10001 FOR SUGGESTED REINFORCING

TEMPLATE NUMBER:

40035\_a

DATE:  
05-28-13