



Product Release Information: XE360 Firmware 01.00.01

Product	XE360
Version Number	01.00.01
Firmware Release Date	April 2025
Customer Support	For more information or support, visit the ENGAGE website.

Attention:

This document contains the **Release Notes** for XE360 device firmware version **01.00.01**. This version includes feature updates and improvements made after XE360 product firmware 01.00.00 released in February of 2025.

Installation and Update Notes:

Device firmware updates are available through the ENGAGE™.

Each lock may be updated to the latest firmware by connecting locally to individual locks with the ENGAGE mobile application.

Firmware versions that will be installed with this update:

- **Main App** **02.03.000003**
- **Reader App** **02.01.000004**
- BLE Application 01.00.536869-BL:02.01.000000-SE:01.02.13
- Main BL 01.00.000001
- Reader BL 02.00.000001

NOTE: The **BOLD** item(s) are updated from the previous release

Other system components versions to be used with this release: (or newer)

- MT20W 41.00.00
- Android Application 4.7.882
- iOS application 3.17.1
- ENGAGE 8.5.2



Who should update?

Allegion suggests that customers utilize the latest firmware release to take advantage of the latest functionality, bug fixes, and security enhancements. We strive to provide the best products and service for our customers.

Specifically, any customer interested in any of the following Recent Changes should update their devices.

Recent Changes:

- Fixed an issue encountered after a PACS Database update
- Fixed an issue where dbManager would not reset the user count after receiving the “deleteAll=1” command
- Fixed an issue where duplicate user records could be added to the database using the add[] JSON tag
- Improved jsonAudit and jsonReport Buffer performance
- Improved HMAC Buffer performance

Revision	COMMENTS	DATE
SES20250415A	Release Notes for XE360 01.00.01	04-15-25